

FIG. 1




FIG. 4

Fig 16





FIG. 3

FIG. 2



| | | |
|-----------|----------|----------|
| APPROVED | O.G FIG. | |
| BY | CLASS | SUBCLASS |
| DRAFTSMAN | SS | 1032 |

+

4/7

FIG. 7 is a perspective view of the structure of FIG. 6, showing the internal bracing members 76 and the side rails 71 and 72.




FIG.-7




FIG.-8

+

| | | |
|-----------|-----------|---------|
| APPROVED | O.G. FIG. | |
| BY | CLASS | DATE |
| DRAFTSMAN | SS | 10/3/56 |

5/7




FIG._9




FIG._10

+

Copyright © 1994 by The McGraw-Hill Companies, Inc. All rights reserved. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, recording, or by any information storage and retrieval system, without permission in writing from The McGraw-Hill Companies, Inc.




FIG.-13

FIG.-12

FIG.-11

+

7/7




FIG.-16

FIG.-15

FIG.-14